

BELZONA GIVES OLD PUMP NEW LEASE OF LIFE

ID: 1006

Industry: Power

Application: CEP-Centrifugal Pumps

Substrate: Cast iron

Products: Belzona® 1311 (Ceramic R Metal)<div>Belzona® 1321 (Ceramic S Metal)</div>

Customer Location: Coal-fired power plant, Croatia

Application Date: April 2007

Problem

Deterioration due to bimetallic corrosion and sea water erosion.



Photograph Descriptions

* Damaged seawater pump , * Applying Belzona® 1311 , * Belzona® 1311 application complete , * Belzona® 1321 applied ,

Application Situation

Sea Water Pump

Application Method

Application was carried out in accordance with Belzona Know-How System leaflets CEP-3 & -5.

Belzona Facts

Due to the pump's condition, a new pump was considered but Belzona application proved to be a long term cost effective alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024