

BELZONA IN THE PRESS

ID: 1007


Industry: *General Industry*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Printing house, Croatia*
Application Date: *March 2006*

Substrate: *Steel*
Products: ** Belzona® 1221 (Super E Metal) ,*

Problem

A screw fell into the printing machine causing damage to the roller.



Photograph Descriptions

* Printing machine Damaged roller with imprint from screw clearly evident Ongoing application Application completed. ,

Application Situation

Printing machine roller.

Application Method

Application was carried out in accordance with a modified version of Belzona System Leaflet MPT-2.

Belzona Facts

Belzona quickly and effectively got the printing machine back to work, saving time and money and most importantly avoiding excessive downtime enabling the printing house to meet its deadlines.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve