

Damage from Trailer landing legs, repaired by Belzona

ID: 10073

Industry: Chemical & Petrochemical

Customer Location: Alfreton

Application: FPA-Floor Problem Areas

Application Date:

Substrate: Concrete

Products: Belzona 4131 (Magma-Screed), Belzona 4911 (Magma TX Conditioner)

Problem

The Landing legs on the 40' trailers had worn depressions into the concrete floors. These were causing problems with fork lift traffic and other vehicles as some of the depressions were over 40mm deep



Showing landing legs causing wear to concrete parking area near loading doors

Areas cleaned and dried, the conditioned with Belzona 4911

In-house training given to their own team to help them carry out simple repairs in-house

Completed with Belzona 4131 and feather edged

Application Situation

The area had to be out of action for as short a time as possible. Belzona 4131 gave an opportunity for the areas to be replaced easily over 1 weekend

Application Method

Cleans and dried the concrete using absorbent kit

All loose and friable material removed

Belzona 4911 applied with short bristled brush

Belzona 4131 applied by gloved hand and compressed using finishing trowel

Belzona Facts

The works were finished in one afternoon and cured before the business re-opened on the Monday morning. The works were carried out under Belzona supervision using their own staff in order to enable them to pursue further repairs as and when they

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

needed to do them

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

