

Concrete repairs to heavy manufacturing floor

ID: 10074

Industry: Heating, Ventilation & Air Conditioning

Customer Location: Doncaster

Application: FPA-Floor Problem Areas

Application Date: March 2022

Substrate: Concrete


Products: Belzona 4131 (Magma-Screed), Belzona 4911 (Magma TX Conditioner)

Problem

Areas of a heavy industrial floor were compromised and had started to break up, some of which had been repaired previously, though these repairs had failed



Showing one of the heavily damaged areas



Cleaning area prior to application



Application of Belzona 4911 TX Conditioner



Completed application using Belzona 4131

Application Situation

Repairs had been attempted before and had continually failed. The Local ASR attended site to offer full training in the application of the Belzona 4000 series.

Application Method

Clean all area

Mix and apply Belzona 4911 TX conditioner

Mix and apply Belzona 4131

Belzona Facts

The local Belzona ASR supported to application and trained the in-house colleagues on the proper procedure to effect a concrete repair. The site was visited earlier this year (2025) and found to be in excellent order

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA®
Repair • Protect • Improve