

# BELZONA REPAIR AND PROTECTION OF STABILISER SHAFT

ID: 101

Industry: *General Industry*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Shipping Company, Monaco*  
Application Date: *1995*

Substrate: *Steel*  
Products: *\* Belzona® 1111 (Super Metal) ,*

## Problem

*Severe pitting corrosion in-board of bearing.*



## Photograph Descriptions

- \* General view of the stabiliser shaft ,
- \* After grit blasting, degree of erosion-corrosion damage clearly evident ,
- \* Application of Belzona® 1111 being completed ,

## Application Situation

Stabilizer shaft

## Application Method

Application was carried out in accordance with Belzona System Leaflet SOS-1.

## Belzona Facts

Belzona was used because our repair could be done without dismantling.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve