

# BELZONA RAPID FLOOR REPAIR

ID: 1018

Industry: General Industry

Customer Location: Box manufacturer, Montgomery, Alabama USA

Application: FPA-Floor Problem Areas

Application Date: January 2007

Substrate: Concrete

Products: Belzona® 4911 (TX Conditioner) <div>Belzona® 4131 (Magma Screed)</div>

## Problem

Hole in floor creating problem for fork lift drivers loading and unloading cardboard for box manufacture.



## Photograph Descriptions

\* Removed concrete from hole , \* Belzona® 4911 being applied , \* & 4. Finished application ,

## Application Situation

Concrete floor in production area

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

The alternative was to saw cut concrete and pour new concrete. That would be more costly because of labor and down time in the area. It was possible to drive over the Belzona applied in morning that night.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve