

Safety nonskid for office entry

ID: 10183

Industry: Buildings & Structures

Customer Location: Houston, TX

Application: FPA-Floor Problem Areas

Application Date: April 2014

Substrate: Concrete

Products: Belzona 5231 (SG Laminate), Belzona 9221 (Surefoot Aggregate White)

Problem

Non-skid safety markings leading into the customers engineering offices was wearing off after 14 years of service. The customer, a long time user of Belzona non-skid solutions was so impressed with the longevity of the 5231 that Belzona was their only choice to refresh the areas.



Worn Belzona 5231 areas from an application applied in January of 2000.

14 year old non-skid application.

Areas refreshed with Belzona 5231 and 9221 Surefoot aggregate.

Refreshed and ready for another 14 years of service.

Application Situation

The customer needed a solution and product that could be applied over the weekend while offices would not be utilized. Belzona 5231 provided a proven method that would cure in time, and be ready to go on Monday morning.

Application Method

The surface was prepared by power washing to remove any loose coatings as well as dirt and debris. A diamond grinder was used to abrade the surface to provide an acceptable substrate. The first coat of 5231 was applied, then 9221 was broadcasted in for nonskid properties. A second coat of 5231 was applied within the overcoat window in accordance with the Belzona instructions for use.

Belzona Facts

The customer was happy to choose Belzona in this situation because of the ease of use, availability, consultant support, and proven durability.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve