

BELZONA REPAIRS RUBBER LINED BRINE TANK

ID: 1020

Industry: *Pulp & Paper*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Steel and Rubber*
Products: *Belzona® 2111 (D&A Hi-Build Elastomer)*

Customer Location: *Paper Mill, Alabama*
Application Date: *February 2008*

Problem

Rubber lining had been damaged locally. It was too costly to get specialist tank repair company to come and make repair.



Photograph Descriptions

* Opening to the tank , * Exposed metal where repair to be made , * Conditioner applied after grinding , * Repair completed with Belzona® 2111 ,

Application Situation

Rubber lined brine tank in ower house of paper mill

Application Method

Application was carried out in accordance with the Belzona Know-How System Leaflet TCC-3.

Belzona Facts

Would have cost over \$2500 for specialist tank company to come make the repair. Used one unit of Conditioner and one unit of Belzona® 2111. Repair was made one day and tank was put back in surface the next day.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024