

4000 TON CHILLER TUBE SHEET PROTECTED WITH BELZONA

ID: 1032

Industry: Heating, Ventilation & Air Conditioning

Application: HEX-Heat Exchangers

Substrate: steel


Products: Belzona® 1121 (Super XL Metal)<div>Belzona® 1321 (Ceramic S Metal)</div>

Customer Location: Auto manufacturer, Wentzville, MO

Application Date: January, 2008

Problem

Eroded 72" dia tube sheet faces with leaks between the tubes & the tube sheet



Photograph Descriptions

* Chiller with ends shrouded for blast cleaning , * Division plate & end cover , * Corked & coated , * Corks removed ,

Application Situation

One of three Carrier chillers used to cool the 80 acre plant.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet HEX-1. A total of 52 units of 3kg plus 70 units of 1kg of Belzona® 1121 and Belzona® 1321 were used.

Belzona Facts

Years of successful Belzona applications, some of them 20+ year old jobs, are still very visible in this plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024