

BELZONA KEEPS CUSTOMERS ROLLING

ID: 1033

Industry: General Industry
Application: SHM-Solids Handling Machinery

Customer Location: Plant rental company, Augusta SC
Application Date: December 2007

Substrate: Rubber
Products: * Belzona® 2311 (SR Elastomer),

Problem

After the rental was returned they saw the damage and needed a repair right away, knowing the unit was booked to go right back out.



Photograph Descriptions

- * Damage to the tire ,
- * After the roughing surface conditioned ,
- * Belzona® 2311 completed repair ,

Application Situation

Tire repair

Application Method

Application was carried out using a modified Belzona Know-How System Leaflet SHM-1. The Surface was roughed with roughing brush, Conditioned then gouges in tire repaired with the Belzona® 2311.

Belzona Facts

Belzona Elastomer was chosen for this job because of its durability, ease of application and how quickly they could get the unit back into the field again.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve