

BELZONA REPAIR OF CONVEYOR BELT

ID: 1037


Industry: Power
Application: SHM-Solids Handling Machinery

Customer Location: Power plant, Bulgaria
Application Date: August, 2002

Substrate: Rubber
Products: Belzona® 2311 (SR Elastomer)

Problem

Mechanical damage on the protector/scrapper was exposing the metal reinforcement



Photograph Descriptions

* View of the conveyor belt facility , * Conditioning with Belzona® 2911 , * Belzona® 2311 used to rebuild the damage ,

Application Situation

5 km conveyor belt for transporting coal to the power plant

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1.

Belzona Facts

The customer required the repair with minimum down-time. Belzona was chosen for its effective simple and fast accomplishment without special equipment as per alternative hot vulcanization method.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve