

BELZONA REBUILDS LIFT PUMP

ID: 1047

Industry: Water / Wastewater
Application: CEP-Centrifugal Pumps
Substrate: Steel
Products: * Belzona® 1311 (Ceramic R Metal) ,
* Belzona® 1321 (Ceramic S Metal) ,

Customer Location: Waste Water Utility, Oklahoma
Application Date: September 2006

Problem

Pump had lost efficiency and had to be pulled. The model was foreign and had a four week lead time for parts.



Photograph Descriptions

- * Eroded impeller ,
- * Impeller reinforced and blasted ,
- * Blasted and coated bowl ,
- * Impeller after balance and rebuild ,

Application Situation

Lift station pump.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets CEP-1, CEP-3 and CEP-5.

Belzona Facts

This impeller and bowl was rebuilt in a local repair shop using Belzona for 40% of the cost of a new one. The customer reported that when reinstalled the check valve has never gone higher!

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve