

# BELZONA PREVENTS SLIPPING IN WASH AREA

ID: 1053

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: Belzona® 4151 (Magma Resins)

Customer Location: Dairy, Oklahoma USA  
Application Date: June, 2006

## Problem

Previous applications of non-slip surfacing had peeled so necessitating a more permanent solution.



## Photograph Descriptions

\* Surface being cleaned , \* First coat , \* Second coat , \* Almost two years later the floor although dirty is 100% intact ,

## Application Situation

Walkway in wash station for casings is always wet.

## Application Method

Application was carried out using a modified version of Belzona Know-How System FPA-3. after thorough cleaning and abrading, two coats of Belzona® 4151 with a colored aggregate were then applied.

## Belzona Facts

This floor is two years old and still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve