

# BELZONA IMPROVES CONVEYER EFFICIENCY

ID: 1067

Industry: General Industry

Application: SHM-Solids Handling Machinery

Customer Location: Automotive company, Slovakia

Application Date: 2006

Substrate: Rubber

Products: Belzona® 2211 (MP Hi-Build Elastomer)

## Problem

Products were sliding on the belt due to incline and smooth surface.



## Photograph Descriptions

\* Slippery belt , \* Application of Belzona® 2211 , \* Steel plates for moulding Elastomer to shape , \* Completed belt ready to work ,

## Application Situation

Elevated conveyer system

## Application Method

The application was carried out in accordance with modified Belzona Know-How System Leaflet SHM-5.

## Belzona Facts

Customer had problems with sliding of products. To change the belt was expensive. Creating cleats/treads with Belzona was quick, cheap and effective solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2024

  
**BELZONA®**  
Repair • Protect • Improve