

BELZONA FLEXIBLE MEMBRANE SEALS LEAKING CONCRETE DECK

ID: 1077

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Exposed aggregate concrete*
Products: *Belzona® 3111 (Flexible Membrane)*

Customer Location: *Property Management Company*
Application Date: *August 1995*

Problem

Water, leaking through the concrete deck, was falling on the cars parked beneath and damaging the paintwork



Photograph Descriptions

* The deck prepared by pressure washing , * After application of Belzona® 3911 to concrete surfaces and Belzona® 3921 Aluminum surfaces (window and door frames), Belzona® 3111 was applied , * View of deck taken in 2005 after 10 years of service ,

Application Situation

Leaking concrete deck over parking garage

Application Method

Application completed in accordance with a modified version of Belzona Know-How System Leaflet RPA-10.

Belzona Facts

Various crack sealing products had been tried with little little to no success.
A recent check in 2008 reveals the deck coating to still be in service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve