

BELZONA ELASTOMER SEALS CONCRETE PARKING DECK

ID: 1080

Industry: *Buildings & Structures*

Application: *FPA-Floor Problem Areas*

Substrate: *Concrete*

Products: ** Belzona® 2221 (MP Fluid Elastomer),*

Customer Location: *Shopping Mall - Vancouver, BC*

Application Date: *November 2007*

Problem

A previous application by another contractor had failed in a very short space of time leading to water entering the shop below.



Photograph Descriptions

- * All joints were ground clean to remove all traces of the failed material ,
- * All joints were conditioned with Belzona® 2911 prior to injecting the Elastomer ,
- * Completed application with all the joints and cracks sealed ,

Application Situation

Various cracks and faulty seams on concrete parking deck.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-6.

Belzona Facts

Heavy rains after the application had been completed revealed that the area was now completely water-tight.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve