

# BELZONA SCREED RESTORES DETERIORATED FLOORS

ID: 1112

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete & Epoxy floor coating*  
Products: *<div>Belzona® 4131 (Magma Screed)</div>*

Customer Location: *Supermarket, British Columbia, Canada*  
Application Date: *2007*

## Problem

*Water trapped underneath the failed coating was causing odour and health concerns.*



## Photograph Descriptions

\* The delaminated coating was removed with scrapers , \* The area was ground with a Vacu-Grinder , \* Application of Belzona Magma Screed in progress , \* Completed application with heat lamps in place . ,

## Application Situation

The red epoxy floor coating was delaminating.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.  
Heat lamps were used to accelerate cure to ensure area ready for use following day.

## Belzona Facts

Belzona Magma Screed provides hard wearing floor covering that was applied overnight so causing minimal disruption to the store.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve