

BELZONA REBUILDS WASTEWATER PUMP IMPELLER

ID: 1116

Industry: Water / Wastewater

Customer Location: Water treatment plant, Des Moines,
Iowa U.S.A.

Application: CEP-Centrifugal Pumps

Application Date: May 2008

Substrate: Steel

Products: <div>Belzona® 1111 (Super Metal)</div><div>Belzona® 1321 (Ceramic S Metal)</div>

Problem

The impeller was badly eroded and damaged due to grit and solids running through the pump



Photograph Descriptions

* Damaged impeller after being baked and grit blasted , * Impeller with wire mesh in place to support Belzona and help form profiles , * Profiles restored with Belzona® 1111 , * Rebuilt impeller being balanced ,

Application Situation

Pump impeller handling raw water.

Application Method

The applications was carried out in accordance with Belzona Know-How System Leaflet CEP-1 & -3.

Belzona Facts

Belzona was chosen to rebuild the impeller at a fraction of the replacement cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024