

BELZONA PROTECTS CHEMICAL CONTAINMENT AREA

ID: 1135

Industry: General Industry
 Application: TCC-Tanks and Chemical Containment Areas
 Substrate: Concrete, Steel
 Products: <div>Belzona® 4111 (Magma Quartz)</div>
 <div>Belzona® 4311 (Magma CR1)</div>

Customer Location: Food Processing plant, France
 Application Date: June 2003

Problem

Heavy deterioration of the concrete due to leakage and contamination during maintenance operations. The integrity of the structure was compromised.



Photograph Descriptions

- * View before repairs ,
- * View of the tank supports ,
- * View after shimming ,
- * Application completed with Belzona® 4311 applied ,

Application Situation

Chemical containment area

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Special attention given to shimming and protecting base of support steelwork.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com


BELZONA
 Repair • Protect • Improve

Belzona Facts

Area brought up to standard to meet required regulations. Additional protection for supports. Repairs easily carried out if required.
Durable: During the last inspection in 2009, the containment area was in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

