

# BELZONA REFURBISHES MILITARY DOG KENNELS

ID: 1142

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Concrete and Cinder Block*  
Products: *Belzona® 4111 (Magma Quartz)<div>Belzona® 5111 (Ceramic Cladding)</div><div>Belzona® 5811 (Immersion Grade)</div>*

Customer Location: *Military Base, North Alabama*  
Application Date: *April 2006*

## Problem

*An easy to clean, hygienic non slip coating required.*



## Photograph Descriptions

\* Prepped and ready to coat , \* Floor and coves covered , \* Almost complete, walls being coated , \* All done! Ready to turn over to the owners ,

## Application Situation

Floors and walls in dog kennels.

## Application Method

This application was performed in accordance with Belzona Know-How System Leaflets FPA-3 & TCC-15.

To create a non-slip surface that did not damage paws, different aggregates were tried before settling on a non-standard Belzona one that was found to be ideal. Coves between wall and floor were formed and Belzona® 5111 provided stain resistant finish.

## Belzona Facts

The Commander tried many different coatings over the years and had not found a suitable coating that stood up to the wear and tear of the dogs. Our Belzona application has been down for 2 years and looks just like new.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024