

BELZONA PEDESTRIAN WALKWAY

ID: 1144

Industry: *Buildings & Structures*

Customer Location: *Hospital, San Bernardino, California
U.S.A.*

Application: *FPA-Floor Problem Areas*

Application Date: *2005*

Substrate: *Asphalt*

Products: *Belzona® 4111 (Magma Quartz)*

Problem

A hard wearing non-slip surface required to provide a safe route into the hospital



Photograph Descriptions

* Walkway marked out and surface prepared , * Belzona system being applied , * Application completed , * Still in excellent condition 2 years later ,

Application Situation

Walkway required for pedestrians crossing from the parking structure to the main door to the Hospital.

Application Method

Application was carried out using a modified version of the Belzona Know-How System Leaflet FPA-8. A slurry mix of Belzona® 4111 tinted white was used.

Belzona Facts

Belzona system provided the hard wearing non-slip surface required in this critical area.
System still in excellent condition when inspected 2 years later.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025