

BONDING FAIRLEADS WITH BELZONA

ID: 1148

Industry: *Marine*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Aluminium and GRP gelcoat*
Products: ** Belzona® 1111 (Super Metal) ,*

Customer Location: *Shipyards, France*
Application Date: *May 2008*

Problem

Fairleads have been dismantled in order to realise repairs to the hull. A rebuilding and bonding material was then necessary to fill gaps when fairleads were replaced.



Photograph Descriptions

- * Fairlead pocket ,
- * Fairlead before application ,
- * Application underway ,
- * Fairlead clamped in place during the cure process ,

Application Situation

37 Meters long Yacht

Application Method

Application was carried out in accordance with a modified Belzona Know How System GSS-9.

Belzona Facts

The pourable chocking option usually considered by the customer could not be applied in this situation due to the thickness of adhesive required. Belzona® 1111 has no limitation in thickness when applied in such an environment,

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve