

OLD APPLICATION MEETS NEW BELZONA APPLICATION

ID: 1174


Industry: Buildings & Structures
Application: FPA-Floor Problem Areas

Customer Location: Railroad in Saint Paul, Minnesota U.S.A.
Application Date: 1996 and 2008

Substrate: Concrete
Products: * Belzona® 4411 (Granogrip) ,
* Belzona® 5231 (SG Laminate) ,

Problem

The floor gets covered in fuel and water causing a slip hazard. Also the cleaning method began attacking the concrete.



Photograph Descriptions

- * Preparing the surface ,
- * Taping off edges ,
- * Patching holes before coating ,
- * Old Belzona® 4411 on ramps meets new Belzona® 5231 on workshop floor ,

Application Situation

Diesel shop floor and ramps

Application Method

Applications was carried out in accordance with Belzona Know-How System Leaflets FPA-3 & FPA-8.

Belzona Facts

The ramps where done over 12 years ago and still in great condition saving time and money spent re-doing them repeatedly with systems. The floor has shown to be a safety benefit that also is easier and faster for crews to clean.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve