

BELZONA SEALS PACKING FACILITY


ID: 1175

Industry: General Industry
Application: RPA-Roof Problem Areas
Substrate: Aluminum
Products: Belzona® 3111 (Flexible Membrane)

Customer Location: Cement Company, Miami, Florida U.S.A.
Application Date: April 2008

Problem

Roof was leaking through the seams and joints.



Photograph Descriptions

* Uncoated seams , * Belzona® 3921 (GSC Conditioner) being applied , * Seams being coated with Belzona® 3111 and reinforced with Belzona® 9311 , * Finished application. ,

Application Situation

Bolted metal roof

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

Belzona Facts

The customer was previously using a low cost silicone sealant with poor results allowing continued damage to expensive packing machinery and controls.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve