

BELZONA CAVITATION DAMAGE REPAIRED ON CRUISE SHIP PROPELLERS

ID: 118

Industry: Marine

Application: SOS-Ships and Offshore Structures

Customer Location: Cruise Ship

Application Date: February 1995

Substrate: Stainless steel

Products: * Belzona® 1311 (Ceramic R-Metal) ,

Problem

Propellers on cruise ship had cavitation damage on all four blades of both propellers.



Photograph Descriptions

- * Starboard propeller after grinding ,
- * #4 starboard propeller after Belzona® 1311 application ,
- * #2 port propeller after Belzona® 1311 application ,

Application Situation

Ship propellers

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet SOS-1.

Belzona Facts

Repairs were accepted by Lloyds Register surveyor and by Russian Certification Society. About 1 kg of Belzona® 1311 (Ceramic R-Metal) (about \$170) was used.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025