

# BELZONA REBUILDS AND PROTECTS EXHAUST ON YACHT

ID: 1181

Industry: Marine

Application: SOS-Ships and Offshore Structures

Customer Location: Shipyard, Monaco


Application Date: November 2008

Substrate: Steel

Products: <div>Belzona® 1511 (Super HT-Metal)</div><div>Belzona® 1391 (Ceramic HT)</div>

## Problem

Severe corrosion caused by hot exhaust gas and salt water, led to critical loss of steel.



## Photograph Descriptions

\* The yacht in dock , \* Initial state of exhaust pipe , \* Pitting clearly evident after blasting , \* Final result after rebuilding with Belzona® 1511 and coating with Belzona® 1391 ,

## Application Situation

Luxury yacht in dock for routine repairs and inspection.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets SOS-1 & -2.

## Belzona Facts

This repair was completed in 2 days.

The only alternative is to change the exhaust pipe. It would have cost much more and taken 2 weeks to complete.

Application was overseen by Lloyds.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve