

# BELZONA BRIGHTENS UP HOSPITAL LAUNDRY FLOOR

ID: 1205

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: Belzona® 5231 (SG Laminate)

Customer Location: Medical Center, Anniston, Alabama USA  
Application Date: December 2007

## Problem

*The coating that was currently on the floor was worn and causing slip hazards for the employees.*



## Photograph Descriptions

\* Floor prior to being prepared , \* Floor after being abraded , \* Belzona® 5231 being applied , \* Completed floor ,

## Application Situation

Hospital was looking to replace coating on laundry room floor.

## Application Method

Application was carried out using a modified Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating and profile the concrete. Areas masked off and Belzona® 5231 Red and Gray used for demarcation.

## Belzona Facts

This customer had to have the application done and ready for foot traffic in one weekend. Because of the quick cure times Belzona® 5231 was a perfect fix. One year later the application still looks great.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve