

UNIVERSITY STUDIES BELZONA FLOOR SOLUTION

ID: 1211

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: <div>Belzona® 4111 (Magma Quartz)</div>
<div>Belzona® 5231 (SG Laminate)</div>

Customer Location: University, St Louis, Missouri U.S.A.
Application Date: Spring 2008

Problem

Floor caused trip hazards for employees and previous coatings required annual refurbishment.



Photograph Descriptions

- * Floor before repairs and coating ,
- * Close up of floor problems ,
- * Holes in floor repaired with Belzona® 4111 ,
- * Floor after coating with Belzona® 5231 ,

Application Situation

Floor areas in service areas/boiler room.

Application Method

Application was carried out in accordance with Belzona Know How System Leaflets FPA-1 & -3.

Belzona Facts

This had been a yearly repair and customer was looking for long term solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve