

BELZONA PROTECTS VERTICAL LIFT PUMP IMPELLER

ID: 1215

Industry: Chemical & Petrochemical
Application: CEP-Centrifugal Pumps
Substrate: Bronze
Products: * Belzona® 2141 (ACR-Fluid Elastomer) ,

Customer Location: Chemical Plant, Texas
Application Date: 2006

Problem

Due to the damage caused by the severe cavitation, costly rebuilding and rebalancing of the impeller was required on at least an annual basis.



Photograph Descriptions

- * Vertical lift impeller with Belzona® 2941 conditioner applied ,
- * Inspection of impeller during coating process ,
- * Coating completed, awaiting installation ,

Application Situation

Open-faced vertical lift pump impeller

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3.

Belzona Facts

Pump still in service and performing satisfactorily almost 3 years later. Annual overhaul on these type pumps can run as much as \$30,000 (3 years approx. \$90,000 savings.) Belzona product was less than \$3,000.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024