

COOLING TOWER REFURBISHED WITH BELZONA

ID: 1223

Industry: Heating, Ventilation & Air Conditioning
Application: TCC-Tanks and Chemical Containment Areas



Customer Location: Hospital, Memphis Tennessee USA
Application Date: 2008

Substrate: Galvanized steel plates

Products: <div>Belzona® 3121 (MR7)</div><div>Belzona® 5811 (immersion Grade)</div><div>Belzona® 1121 (Super XL Metal)</div>

Problem

The corroded and holed areas needed repair and the cold water basin needed sealing to prevent leakage and future corrosion.



Photograph Descriptions

* Cooling Tower overview , * Blasting the Cold Water Basin , * Belzona® 3121 over the seams , * Final coat of Belzona® 5811 ,

Application Situation

Cooling Tower with severe corrosion in cold water basins

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-1, TCC-5 and RPA-1. The steel was grit blasted, holes repaired with Belzona® 1121. Seams sealed with Belzona® 3121 and Belzona® 5811 applied to provide overall corrosion protection.

Belzona Facts

A new tower would cost \$80,000 and downtime would have been weeks. The hospital needed a 5 day turnaround which was achieved using Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024