BELZONA "DELIVERS" A SANITARY FLOORING SOLUTION

ID: 1232

Industry: Buildings & Structures Customer Location: Church charity organization, Texas

Application: FPA-Floor Problem Areas Application Date: 2006

Substrate: Plywood

Products: * Belzona® 5811 (Immersion Grade),

Problem

The raw plywood floor with no sealant would be difficult to maintain and keep clean in an area that required a very sanitary environment.







Photograph Descriptions

- * The portable birthing center,
- * Floor prior to coating with walls taped off,
- * Finished Belzona® 5811 flooring application ,

Application Situation

Charitable members of a Texas church were fabricating a portable birthing trailer that would eventually be shipped to Guatemala in an effort to offer a sanitary medical facility for use in an impoverished area that suffered from a high birthing mortality rate.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The walls were taped off approximately 2 inches up the vertical edge, sanded, cleaned then coated with two coats of Belzona® 5811 with minimal Surefoot aggregate added during the first coat process.

Belzona Facts

This product was donated through the Belzona Houston Distributorship and one of its Consultants at no cost to the church mission organization. An alternative to 5811 was to purchase an inferior floor coating from a hardware store which would not have had the same trouble-free application or long-lasting result.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve