

BELZONA REPAIRED RECYCLING DRUM LASTS 12 YEARS

ID: 1266

Industry: Pulp & Paper

Application: TCC-Tanks and Chemical Containment

Areas

Substrate: Carbon Steel

Products: * Belzona 1311 (Ceramic R-Metal),

* Belzona 1321 (Ceramic S-Metal),

Problem

Bi-metallic corrosion on approximately 70% of the weld.







Customer Location: USA

Application Date: April 1997



Photograph Descriptions

- * Remaining Belzona 1311 from application 12 years ago,
- * Additional remaining Belzona 1311 from original application,
- * Remaining Belzona 1321 from application 12 years ago,
- * Additional remaining Belzona 1321 from original application,

Application Situation

A paper mill recycling drum (30 long and 10 diameter) used to recycle newsprint. It operates 24 hours a day, 7 days a week at 120°F and pH 10-11.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet TCC-5.

Belzona Facts

The application literally saved millions of dollars in replacement costs and downtime. The pictures show how much Belzona Ceramic R-Metal is left protecting the incompatible welds and Ceramic S-metal is left protecting the surface of the steel. Inspection of the application after 12 years of continuous service and sandblasting with coal slag proves that Belzona provided the right solution for

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



the problem.

www.belzona.com