

BELZONA SAVES RECYCLING DRUM FOR SECOND TIME

ID: 1267

Industry: Pulp & Paper Customer Location: Paper Mill, North America
Application: TCC-Tanks and Chemical Containment Application Date: 1997 & March, 2009

Areas

Substrate: Carbon steel and incompatible weld.

Products: * Belzona 1311 (Ceramic R-Metal) ,

* Belzona 1321 (Ceramic S-Metal),

Problem

Bi-metallic corrosion on approximately 70% of the un-protected welds found in 1997. Belzona system applied and inspection of the application after 12 years proves that Belzona provided the right solution for the problem. Belzona was selected to be re-applied to further protect the drum.









Photograph Descriptions

- * Original application in 1997,
- * After grit blasting Belzona still protecting the critical welds after 12 years. ,
- * Belzona 1311 being applied,
- * Completed project after application of Belzona 1321,

Application Situation

Recycling Drum (30ft long and 10ft diameter) used to recycle newsprint. Drum is operated 24 hours a day, 7 days a week at 120°F and pH 10-11.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-5.

Belzona Facts

The original Belzona application has provided 12 years protection in this corrosive and abrasive environment and saved literally

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®