

BELZONA PROTECTS OIL GAS SEPARATORS

ID: 127

Industry: Oil & Gas

Customer Location: International Equipment Manufacturer
to the Oil Industry

Application: TCC-Tanks and Chemical Containment
Areas


Application Date: 1994

Substrate: Steel

Products: * Belzona® 1391 ,

Problem

Severe deterioration to the internal surfaces of the vessels due to erosion-corrosion and SRB attack.



Photograph Descriptions

- * General view of separator ,
- * Application of Belzona® 1391 underway in a confined internal space ,
- * Completed application to all internal surfaces of the separator ,

Application Situation

Two standard designs of test separators used around the world and particularly in the Middle and Far East.

Application Method

The application was carried out in accordance with the Belzona Know-How Leaflet TCC-3

Belzona Facts

Belzona® 1391 is now specified by this company for refurbishment of oil/gas separators and also for new separators. The alternative is replacements at \$200,000. Belzona refurbishment saves about \$150,000 per separator. Total worldwide refurbishment programme is going to be worth approximately \$2 million.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve