

BELZONA SEALS HYDRAULIC LEAK

ID: 1297

Industry: General Industry

Customer Location: Manufacturer of Stone and Marble Products

Application: VPF-Valves, Pipes and Fittings


Application Date: August, 2009

Substrate: Steel

Products: * Belzona® 1111 (Super Metal) ,

Problem

Hydraulic pipe had started to leak causing the fluid to drip onto the electrical circuit panel, causing a shutdown.



Photograph Descriptions

- * Leaking weld joint ,
- * Surface preparation ,
- * Completed repair ,

Application Situation

Hydraulic system of press for stone products

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a. A wrap using the Belzona® 1111 with Belzona® 9341 (Reinforcement Tape) was used to encapsulate the leaking weld.

Belzona Facts

Repair was able to stop the leak and get the operating press back up and running in a short amount of time minimizing disruption to production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve