

BELZONA FIXES DRAINAGE PROBLEM

ID: 1345

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 5811 (Immersion Grade) ,

Customer Location: Office Building, Ontario Canada
Application Date: May, 2009

Problem

Previously installed coating system had failed and was stopping the water or anything else from draining out.



Photograph Descriptions

- * Water and trash not able to escape ,
- * Removing the old system ,
- * Grinding back to white concrete ,
- * Belzona® 5811 applied ,

Application Situation

Parking garage storm drain

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The failed coating was ground out to expose clean concrete before application of the Belzona® 5811.

Belzona Facts

Customer was very happy with the solution. They now have a drain that gets rid of the water and their worries.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve