BELZONA KEEPS THE BEANS DRY

ID: 1361

Industry: General Industry Customer Location: Bean processor, Manning, Iowa

Application: CEP-Centrifugal Pumps Application Date: April 2009

Substrate: steel and concrete

* Belzona® 3921 (GSC) ,

* Belzona® 3111 (Flexible Membrane),

* Belzona® 6111 (Liquid Anode),

Problem

Products:

Water ingress between tank and concrete tank base. For several years tar was applied but continually failed.









Photograph Descriptions

- * Belzona® 6111 applied and Belzona® 3921 being applied,
- * First coat of Belzona® 3111 with Reinforcing sheet being applied,
- * Completed application,
- * Completed application, general view,

Application Situation

75 ft. diameter soybean storage bin

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet GSS-3.

Belzona Facts

Applying tar around the tank base had proven to be very temporary and unsuccessful. Belzona® 6111 provides excellent corrosion protection to steel wall and Belzona® 3111 provides flexible weatherproof seal. Customer was so pleased with the results of Belzona that 3 more tanks are scheduled for the same treatment.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®