

PUMP BELL CASING REPAIRED AND PROTECTED WITH A LONG TERM BELZONA SOLUTION

ID: 1369

Industry: Power
Application: CEP-Centrifugal Pumps
Substrate: Cast Iron
Products: * Belzona® 1311 (Ceramic R-Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,
* Belzona® 5811 (Immersion Grade) ,

Customer Location: National Electricity Provider, Malta
Application Date: May 2000

Problem

Efficiency losses and pump breakdown due to severe erosion-corrosion of the single vertical axial flow pump (7090 m³/h). Prior to the Belzona solution the client had to replace or repair the pump components annually. As a significant local electricity supplier, downtime of this critical equipment caused major problems.



Photograph Descriptions

- * Original system after 1 year in service ,
- * The finished Belzona application ,
- * Cavitation damage in the swept area ,
- * Ready to go back into service after touch up ,

Application Situation

Sea water cooling system pump for a 60 MW turbine.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflets CEP-5, CEP-3 and CEP-4.

Belzona Facts

The original bell lining was failing on an annual basis, leading to pitting corrosion and regular replacement. The Belzona repair vastly

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

improved reliability and performance. The pump casing, liner and diffuser were also repaired and coated, internally and externally. Yearly touch up is required of the sacrificial coating in the swept area due to cavitation damage. original Belzona protected bellmouth still in service after nine years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

