

# BELZONA KITCHEN REPAIR KEEPS THE STUDENTS GOING

ID: 1381

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Metal, concrete and tiles*  
Products: *\* Belzona® 4111 (Magma Quartz) ,*

Customer Location: *University, France*  
Application Date: *June 2004*

## Problem

*The tiles were degraded around the stainless steel grate. Following a health and safety inspection, the hygiene of the kitchen was reported so urgent action needed to be taken.*



## Photograph Descriptions

- \* Application situation 1 before repair ,
- \* Application situation 2 before repair ,
- \* Application situation 1 after repair ,
- \* Application situation 2 after repair ,

## Application Situation

Kitchen serving the restaurant for the University students.

## Application Method

The application was carried out following the Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

The Belzona solution offers several advantages to the customer. The excellent adhesion onto different substrates (metal, concrete &

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)



tile). The easy to clean surface, proven to be a hygienic solution. It is also resistant to the cleaning liquids used. The Belzona® 4111 is resistant to the pedestrian & trolley traffic in this environment and after 5 years in service, the repair is still in perfect condition.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

