

BELZONA KITCHEN REPAIR KEEPS THE STUDENTS GOING

ID: 1381

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Metal, concrete and tiles
Products: * Belzona® 4111 (Magma Quartz) ,

Customer Location: University, France
Application Date: June 2004

Problem

The tiles were degraded around the stainless steel grate. Following a health and safety inspection, the hygiene of the kitchen was reported so urgent action needed to be taken.



Photograph Descriptions

- * Application situation 1 before repair ,
- * Application situation 2 before repair ,
- * Application situation 1 after repair ,
- * Application situation 2 after repair ,

Application Situation

Kitchen serving the restaurant for the University students.

Application Method

The application was carried out following the Belzona Know-How System Leaflet FPA-1.

Belzona Facts

The Belzona solution offers several advantages to the customer. The excellent adhesion onto different substrates (metal, concrete &

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

tile). The easy to clean surface, proven to be a hygienic solution. It is also resistant to the cleaning liquids used. The Belzona® 4111 is resistant to the pedestrian & trolley traffic in this environment and after 5 years in service, the repair is still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

