

# BELZONA KITCHEN REPAIR KEEPS THE STUDENTS GOING

ID: 1381

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Metal, concrete and tiles  
Products: \* Belzona® 4111 (Magma Quartz) ,

Customer Location: University, France  
Application Date: June 2004

## Problem

The tiles were degraded around the stainless steel grate. Following a health and safety inspection, the hygiene of the kitchen was reported so urgent action needed to be taken.



## Photograph Descriptions

- \* Application situation 1 before repair ,
- \* Application situation 2 before repair ,
- \* Application situation 1 after repair ,
- \* Application situation 2 after repair ,

## Application Situation

Kitchen serving the restaurant for the University students.

## Application Method

The application was carried out following the Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

The Belzona solution offers several advantages to the customer. The excellent adhesion onto different substrates (metal, concrete &

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

tile). The easy to clean surface, proven to be a hygienic solution. It is also resistant to the cleaning liquids used. The Belzona® 4111 is resistant to the pedestrian & trolley traffic in this environment and after 5 years in service, the repair is still in perfect condition.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

