

BELZONA RESURFACES BRAKE TEST ROLLERS

ID: 1435

Industry: General Industry

Customer Location: State Road Transport Research Institute,
Ukraine

Application: SHM-Solids Handling Machinery

Application Date: June 2007

Substrate: Steel

Products: * Belzona® 1821 (Fluid Metal) ,
* Belzona® 9211 (Supergrip Aggregate) ,

Problem

Worn original anti-slip coating on the brake rollers.



Photograph Descriptions

- * The worn brake test rollers ,
- * Application of Belzona Grip system ,
- * Completed application ,
- * Picture after 2 years in service and more than 12,000 brake tests ,

Application Situation

Rollers of the Brekon 131-4S type car brake testing rig.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-12.

Belzona Facts

Belzona application avoided the replacement costs and outage of equipment. Between 2007 and 2009, more than 12.000 brake tests have been carried out, which was a very satisfactory result for the client. A Testimonial letter is available from the customer about this application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025