

BELZONA STOPS ANNULAR PLATE EXTERNAL CORROSION


ID: 1448

Industry: Oil & Gas
Application: GSS-Gaskets, Seals and Shims
Substrate: Concrete & Steel
Products: * Belzona® 3111 (Flexible Membrane),

Customer Location: LPG Tank Farm, Sharjah, UAE
Application Date: March 2006

Problem

Annular plate suffering external corrosion from contaminated condensation running down the walls plus the sea water environment gathering between steel and concrete plinth.



Photograph Descriptions

- * Drawing of insulated LPG tank showing areas requiring protection ,
- * Application of the Belzona® 3111 System ,
- * Close up of condensation running off the annular plate ,
- * View of completed application ,

Application Situation

Liquid gas tanks.

Application Method

The application was carried out in accordance with Belzona Know How System Leaflet GSS-3.

Belzona Facts

Many tank farms in the UAE have used Belzona for tank base sealing and is a proven cost effective solution that avoids the ultimate

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



solution of tank bottom replacement.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

