# RESEATING NEW RUDDER BEARING WITH BELZONA

ID: 1478

Industry: Marine Customer Location: Dockyard, Bulgaria

Application: SOS-Ships and Offshore Structures Application Date: June, 2010

Substrate: Cast Iron housing & Bronze bearing
Products: \* Belzona® 1221 (Super E-Metal),

\* Belzona® 1321 (Ceramic S-Metal),

#### **Problem**

Corrosion damage and severe wear led to destruction of the old bearing and irregular form of the housing leading to increased annular space between the new manufactured bearing and the housing.









## **Photograph Descriptions**

- \* Bronze bearing machined and ready to be inserted in to the housing,
- \* Centralizing of the bearing in progress,
- \* Bae of bearing sealed with Belzona® 1221,
- \* Finished application after injection of Belzona® 1321,

### **Application Situation**

Installation of new bronze bearing in oversized bearing housing.

## **Application Method**

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-9. The injection was through flexible hose placed into the four channels made in the back of the bearing.

#### **Belzona Facts**

Belzona saved time and money against expensive machining of the housing and supply of larger bronze bush. No alternative was fast enough to compete. This standard repair procedure eliminates galvanic corrosion and provides long term location of the bearing.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.



www.belzona.com