## **BELZONA ENHANCES EFFICIENCY OF NEW PUMPS**

ID: 1479

Industry: Water / Wastewater Customer Location: Water supply company, Bulgaria

Application: CEP-Centrifugal Pumps Application Date: February - April, 2010

Substrate: Cast iron case and bronze impeller

Products: \* Belzona® 1111 (Super Metal) ,

\* Belzona® 1341 (Supermetalglide) ,

**Problem** 

Need of corrosion/erosion protection and increased pumping efficiency







### **Photograph Descriptions**

- \* Grit blasted casing,
- \* Preparation of rebate grooves,
- \* First coat of Belzona® 1341 applied ,
- \* Finished application with second coat of Belzona® 1341,

# **Application Situation**

New double end suction centrifugal Worthington pump

#### **Application Method**

Application procedures were carried out in accordance with Belzona Know-How System Leaflets CEP-3 and CEP-10.

#### **Belzona Facts**

As a result of applied Belzona efficiency enhancement coating a reduced power consumption of 35 kWh was registered and efficiency was increased to 3.5% at duty point. Two new pumps were coated with Belzona during this application period.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015

Belzona products are
FS 695214

ISO 14001:2015

Belzona products are
manufactured under an ISO
9000 Registered Quality
EMS 695213

Management System.

BELZONA®
Repair • Protect • Improve