

# BELZONA REPAIRS OIL LEAK ON TRANSFORMER FIN


ID: 1483

Industry: *Power*  
Application: *VPF-Valves, Pipes and Fittings*  
Substrate: *Steel*  
Products: *\* Belzona® 1161 (Super UW-Metal) ,*

Customer Location: *Electricity Distribution Co. UK*  
Application Date: *2008*

## Problem

*Oil leaking from fins*



## Photograph Descriptions

- \* General view of the transformer ,
- \* Close up of oil leak area ,
- \* Completed application. Leak sealed with Belzona® 1161 ,

## Application Situation

Oil cooled electrical transformer

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

## Belzona Facts

The costly need to drain down the oil to effect a repair was eradicated. The Belzona repair was carried out in less than 2 hours and has proven to be totally successful.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

