

PROTECTION OF BOILER FEED PUMPS WITH BELZONA® 1391

ID: 149

Industry: Chemical & Petrochemical
Application: CEP-Centrifugal Pumps
Substrate: Steel
Products: * Belzona® 1391 ,

Customer Location: Chemical Plant in Poland
Application Date: September 1995

Problem

Erosion on the impellers and casing.



Photograph Descriptions

- * Application underway on one of the impellers. ,
- * Application complete. ,
- * Pump in service ,

Application Situation

Six stage boiler feed pumps operating at 105°C (220°F) and 50 bar pressure at 2950 rpm.

Application Method

Application carried out in accordance with Belzona Know-How system CEP-3.

Belzona Facts

A total of five pumps have now been coated and original pump is still performing satisfactory after four years in service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve