

# BELZONA STOPS LEAK DRAIN PIPE AND HOT WELL PUMP

ID: 1498

Industry: *Water / Wastewater*

Application: *HEX-Heat Exchangers*

Substrate: *Metal Steel*

Products: *\* Belzona 1161 (Super UW Metal) ,*

*\* Belzona 1291 (ES-Metal) ,*

*\* Belzona 9341 (Reinforcing Tape) ,*

Customer Location: *Illinois, USA*

Application Date: *December 2008*

## Problem

*Leaking drain pipe and hot well pump at Water Treatment Plant*



## Photograph Descriptions

- \* 1. Overview of the large sized hole on drain pipe ,
- \* 2. To seal with Belzona 1161 ,
- \* 3. Live leaks of hot well pump ,
- \* 4. Stop leak with Belzona 1291 and Belzona 1161 ,

## Application Situation

Drain pipe and hot well pump of a condenser

## Application Method

The application was carried out in accordance with a modified of Belzona Know-How System Leaflet HEX-9 and CEP-6 . First, Belzona 1291 was used to stop the leak, then Belzona 1161 along with Belzona 9341 covered the area.

## Belzona Facts

The traditional repair solution is not appropriate and loss a lot of time and cost, but Belzona solution is quick and easy, especially, can help the client reduce downtime and replacement cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve