

BELZONA SEALS GASOLINE STORAGE TANK

ID: 1499

Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona® 1161 (Super UW Metal) ,

Customer Location: Petrochemical plant, Ontario, Canada
Application Date: Summer 2008

Problem

Water was collecting on this large reinforcement seam causing extensive corrosion.



Photograph Descriptions

- * Large corrosion area ,
- * Severity of corrosion clearly evident ,
- * Use of crane lift to access repair area ,
- * Completed Application ,

Application Situation

A large gasoline storage tank

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. The application was completed from the support equipment (crane).

Belzona Facts

Belzona® 1161 was used due to the difficulty in accessing and removing all condensation in the repair area. The application is in excellent condition until today without any problems.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve