

RUBBER PUMP LINERS REPAIRED WITH BELZONA

ID: 1505

Industry: *Mining & Quarrying*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Mine, Namibia*
Application Date: *July 2009*

Substrate: *Rubber*
Products: ** Belzona® 2111 (D&A High-Build Elastomer),*

Problem

Slurry product destroys rubber liners in 3 weeks.



Photograph Descriptions

* Damaged rubber liner Rubber liner being coated with Belzona® 2111 Rubber liner after application of Belzona® 2111 ,

Application Situation

Rubber liners in Slurry pump

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet SHM-9. Belzona Roughing Brush used to prepare surface before Conditioning then rebuilding with Belzona® 2111.

Belzona Facts

The rubber liners coated with Belzona® 2111 are currently lasting 3 times longer than OEM parts. The cost to repair is also lower than a new liner.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024